

Street #	Street Name	Suburb	Building Name	ACP?	ACP Type	Comments
5	Howe Street	Auckland Central	Urba Residences	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
8	Mahuhu Crescent	Auckland Central	AECOM House	Yes	ACP FR	The cladding is solid Aluminium sheet type of panel. The building has types 6 and 7 fire alarm systems, smoke detectors and automatic fire sprinklers
15	Nelson Street	Auckland Central	Columbia Apartments	Yes	ACP FR	The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
17	Putney Way	Manukau	Twin Towers	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
21	Pitt Street	Auckland Central	BECA House	Yes	ACP FR	The building has type 6 fire alarm system, smoke detectors and automatic fire sprinklers
80	Broadway	Newmarket		Yes	ACP FR	The building does have ACP cladding to the Northern elevation only. The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
156	Vincent Street	Auckland Central	Eclipse Apartments	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
188	Hobson Street	Auckland Central	Oaks on Hobson / VR Apartments	Yes	ACP FR	The building has types 8, 15, 16 and 18 fire alarm systems, smoke detectors and automatic fire sprinklers
206	Victoria Street West	Auckland Central	Victoria St Carpark	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
221	Ponsonby Road	Grey Lynn		Yes	ACP FR	The building has a fire alarm system
1	Fanshawe Street	Auckland Central	NZI Centre	Yes	ACP FR	The building does have ACP material, primarily on the building's soffit and parapets. The cladding is mainly glazed curtain wall. The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
10	Tapora Street	Auckland Central	QUBA Apartments	Yes	ACP FR	The cladding on the building is a combination of ACP, Fibre cement sheet, concrete panels and stone claddings. The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
10-26	Jellicoe St	Auckland Central		Yes	ACP FR	The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
120-130	Albert St	Auckland Central	Crowne Plaza	Yes	ACP FR	The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
121-123	Remuera Rd	Remuera		Yes	ACP FR	The building does have elements of ACP cladding. The building is also clad in Powder Coated Aluminium and precast aggregate concrete
135	Albert St	Auckland Central	Auckland Council HQ	Yes	ACP FR	The building has a type 6 fire alarm system, smoke detectors, automatic fire sprinklers and stair pressurisation
135	Hobson Street	Auckland Central	Imperial Gardens	Yes	ACP FR	The building does have ACP cladding mainly as a decorative feature. The building also has a fire alarm and automatic fire sprinklers
1-7	The Strand	Takapuna	Strand Plaza Building	Yes	ACP FR	The building has a type 4 fire alarm system, smoke detectors and automatic fire sprinklers
189	Hobson Street	Auckland Central	Stanford Apartments	Yes	ACP FR	The building does have ACP incorporated into its cladding along with precast concrete panels. The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
196	Hobson Street	Auckland Central	The Hobson Apartments	Yes	ACP FR	The building has ACP cladding to approximately 40% of the building. The remainder of the building is clad mainly with Ventclad a solid metal profile with a stone veneer. The building has a fire alarm system and automatic fire sprinklers
204	Quay Street	Auckland Central		Yes	ACP FR	The building has a fire alarm, smoke detectors, and automatic fire sprinklers
2-16	Takutai Square	Auckland Central	Britomart East	Yes	ACP FR	The building does have ACP cladding mainly as a decorative feature. The building has a fire alarm and automatic fire sprinklers
235-237	Broadway	Newmarket		Yes	ACP FR	The building has a type 3F fire alarm system and smoke detectors
2-4	Graham Street	Auckland Central	NZME	Yes	ACP FR	The building has ACP incorporated into the curtain wall cladding. The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
26	The Warehouse Way	Northcote		Yes	ACP FR	The building has a type 6 fire alarm systems, smoke detectors and automatic fire sprinklers
26-40	Totara Ave	New Lynn	Merchant Quarter Residential Tower	Yes	ACP FR	The building does have ACP cladding on one elevation. The majority of the cladding is precast concrete. The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
28	The Warehouse Way	Northcote		Yes	ACP FR	The building has a type 4 fire alarm systems and smoke detectors
29	Apollo Drive	Albany		Yes	ACP FR	The building has a type 4 fire alarm system and smoke detectors
291-297	Queen Street	Auckland Central	Sky World	Yes	ACP FR	The building has a type 7 fire alarm system, heat detectors, and automatic fire sprinklers
3	Morningside Drive	St Lukes		Yes	ACP FR	The building has a type 3 fire alarm system and smoke detectors
430-432	Queen Street	Auckland Central	Volt Apartments	Yes	ACP FR	The building has a fire alarm system, smoke detectors and automatic fire sprinklers
438	Queen St	Auckland Central	Queens Square Apartments	Yes	ACP FR	The building has types 5, 6, 7, 9, ,14, 15, 16, and 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
49-55	Anzac Ave	Auckland Central	Seaview Apartments	Yes	ACP FR	The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
52	Sale Street	Auckland Central	Sales St Residences	Yes	ACP FR	The ACP is of the Fire Resistant (FR) solid Aluminium sheet type of panel. The building has types 4, 5, 6 and 7 fire alarm systems, smoke detectors and automatic fire sprinklers
53-59	Cook Street	Auckland Central	Aura Apartments	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
59-65	Portage Rd	New Lynn		Yes	ACP FR	The building does have limited ACP cladding to the North and South façade elevations only. The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
75	Victoria Street West	Auckland Central	Victoria Residence	Yes	ACP FR	The building has a type 7 fire alarm system, smoke detectors and automatic fire sprinklers
96-108	Line Road	Glen Innes	Te Oro Building	Yes	ACP FR	The building has a type 4 fire alarm system with smoke detectors
2	Park Road	Grafton	Various buildings from Auckland Hospital	Yes	ACP FR & PE	Building 32 has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers. Building 31 is less than 25m in height, has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers. Building 33 is of low risk and limited concern due to it being a carpark building that is largely open on all sides. The ACP is limited to stair and lift shaft only. Building 33 has a type 2 fire alarm system. Building 1 has a low risk and limited concern due to the ACP used as a decorative feature to the front entrance canopy. Building 1 has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers. Building 2 has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers. Building 8 has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers. Building 8 Radiology bunker extension has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers.
6	Henderson Valley Road	Henderson	Civic Centre Administration Building	Yes	ACP PE	The building has ACP cladding located on limited areas of the façade, mainly on the soffit. The building has a fire alarm system and automatic fire sprinklers

110	Customs Street West	Auckland Central	Oceania & Eastern Building	Yes	ACP PE	The building is also clad in precast concrete panels and Hardiflex sheets. The building has a type 2E fire alarm system, smoke detectors, and automatic fire sprinklers
125	Customs Street West	Auckland Central	Viaduct Point Apartments	Yes	ACP PE	The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
130	Anzac Street	Takapuna	Shoal Haven Apartments	Yes	ACP PE	ACP cladding extends around the balcony columns and is in vertical bands adjoining adjacent units and separated by the balconies. Cladding also consists of pre-cast concrete panels; the balconies are lined internally with fibre cement sheet. The building has types 3 and 5 fire alarm systems including smoke detectors
167	Victoria Street West	Auckland Central	Spark Centre	Yes	ACP PE	The building does have a limited amount of ACP cladding detailed in the exterior soffit. The building is mainly clad in curtain wall glazing and selected stone façade. The building has a types 4, 7 & 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
188	Quay Street	Auckland Central	PWC building	Yes	ACP PE	The building does have ACP cladding located in 1meter wide bands separated by glazing. The majority of the building is clad in glass. The building has types 7, 9,13, 14, 15, 16, 18 and 19 fire alarm systems, smoke detectors, and automatic fire sprinklers
100	Victoria Street West	Auckland Central	TVNZ	Yes	ACP PE	The building has a type 7e fire alarm system and smoke detectors and automatic fire sprinklers
12	Grafton Rd	Auckland Central	Owen G Glenn Building	Yes	ACP PE	The building has types 4, 6 and 8 fire alarm systems, smoke detectors, and automatic fire sprinklers
127-129	Hobson Street	Auckland Central	Quest Apartment Hotel	Yes	ACP PE	The building has ACP cladding located on the top four levels. The building is mainly clad in Titanboard. The building has automatic fire sprinklers and a fire alarm system
135-137	Vincent Street	Auckland Central	Dynasty Gardens Apartments	Yes	ACP PE	The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
14-18	Lovell Court	Rosedale		Yes	ACP PE	The building is also clad in, pre-cast concrete panels, profile colour steel and Solasafe 5540 industrial polycarbonate sheeting. The building has types 3f & 4f fire alarm systems and smoke detectors
17	Antares Place	Rosedale	AUT Millenium	Yes	ACP PE	The building has types 4, 6 & 7 fire alarm systems, smoke detectors, and automatic fire sprinklers
176	Broadway	Newmarket	Queens Lodge	Yes	ACP PE	The building is also clad in precast concrete panels and James Hardie Titan sheets. The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
2	Gillies Ave	Newmarket		Yes	ACP PE	The building is also clad in Aluminium perforated metal sheets, pre-cast concrete panels and fibre cement sheets. The building has a types 3, 15, 16 & 18c fire alarm systems and smoke detectors
212	Universal Dr	Henderson		Yes	ACP PE	The building has a type 3 fire alarm system
2-38	Great North Road	Grey Lynn		Yes	ACP PE	The building has a type 4 fire alarm system and smoke detectors
415-427	Queen Street	Auckland Central	Kiwi On Queen	Yes	ACP PE	The building has types 3, 7, 15, 16 and 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
45-49	Hobson Street	Auckland Central	H47 Apartments	Yes	ACP PE	The building has automatic fire sprinklers and a fire alarm system
60	Stanley St	Parnell		Yes	ACP PE	The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
64	Apollo Drive	Albany		Yes	ACP PE	The building has a type 4 fire alarm system and smoke detectors
76-84	Albert St	Auckland Central	City Garden Apartments	Yes	ACP PE	The building has types 7e, 13, 15, 16, 18, & 20 fire alarm systems, smoke detectors and automatic fire sprinklers
79-85	Central Park Drive	Henderson	Waitakere Stadium	Yes	ACP PE	The building has automatic fire sprinklers and a fire alarm system
9-15	Tamariki Ave	Orewa	Nautilus	Yes	ACP PE	The Nautilus re-clad work will involve removal of the current cladding and replacement with a fire resistant panel consisting of two sheets of adhered aluminium with no core
9-17	Byron Ave	Takapuna	Spencer on Byron	Yes	ACP PE	The Spencer on Byron re-clad work will involve removal of the current cladding and replacement with a fire resistant panel consisting of two sheets of adhered aluminium with no core
1	Barrys Point Road	Takapuna	B&O Building	Yes	ACP type not established	The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
2	Augustus Terrace	Auckland Central		Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the front entry canopy and signage. The building has a type 3 fire alarm system and smoke detectors
17	Ronwood Ave	Manukau		Yes	ACP type not established	The building has a type 4 fire alarm system and smoke detectors
49	Wellesley Street East	Auckland Central	AUT	Yes	ACP type not established	The building has types 4, 11, 12, 14, 15 & 16 fire alarm systems, smoke detectors and automatic fire sprinklers
56	Wakefield Street	Auckland Central	Oracle Tower, AUT Wilson Carpark	Yes	ACP type not established	The building has types 6, 9, 15, 16, 19 & 20 fire alarm systems, smoke detectors, and automatic fire sprinklers
66	Sale Street	Auckland Central		Yes	ACP type not established	The building does have a limited amount of ACP cladding. The building is predominantly clad in 9mm Titan Board and Plaster on Hardibacker. The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
71	Symonds Street	Auckland Central	Wall Street Tower	Yes	ACP type not established	The building is predominantly clad in glass. The building has types 4, 14, 15, 16 & 18 fire alarm systems and smoke detectors
81	Carlton Gore Road	Newmarket	Fidelity Life Building	Yes	ACP type not established	The building has a type 3 fire alarm system, smoke detectors, and automatic fire sprinklers
82	Wyndham Street	Auckland Central	IBM Centre	Yes	ACP type not established	The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
123	Carlton Gore Road	Newmarket		Yes	ACP type not established	The building has automatic fire sprinklers and a fire alarm system
136	Customs Street West	Auckland Central	The Parc	Yes	ACP type not established	the building has type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
147	Hobson Street	Auckland Central	Harvard on Hobson	Yes	ACP type not established	The building does have ACP cladding located on the spandrels and columns. The building is also clad in precast concrete and glass. The building has types 7, 15, 16 and 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
155	The Strand	Parnell		Yes	ACP type not established	The building does have a limited amount of ACP material, restricted to decorative features. The building has a fire alarm system
171	Hobson Street	Auckland Central		Yes	ACP type not established	The building is also clad in pre-cast concrete panels and glazing. The building has a type 4 fire alarm system and smoke detectors
396	Queen Street	Auckland Central	ACG House	Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the spandrels. The building is predominantly clad in marble and glass. The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
1	Queen Street	Auckland Central	HSBC	Yes	ACP type not established	The building does have ACP cladding limited to the corners of the building and decorative features. The building is mainly clad in natural stone and fibre cement sheeting. The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
1	The Warehouse Way	Northcote		Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the parapet and corners of the building. The building has a type 2 fire alarm system and smoke detectors

100-120	Beaumont Street	Auckland Central	The Westhaven	Yes	ACP type not established	The building does have a limited amount of ACP cladding mainly for decorative features. The building has types 3 & 4 fire alarm systems and smoke detectors
109-125	Albert St	Auckland Central	Skycity Convention Centre & Grand Hotel	Yes	ACP type not established	The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
12A	Northcroft Street	Takapuna	Vero Building	Yes	ACP type not established	The building has a type 3 fire alarm system and smoke detectors
13-21	Hobson Street	Auckland Central		Yes	ACP type not established	The building is also clad in metal wall and tile cladding. The building has significant fire safety systems, including fire alarm system, laser smoke detectors, stair pressurisation, high expansion foam suppression system, UV and IR detectors, and automatic fire sprinklers
15-17	Sturdee Street	Auckland Central	Viaduct Carpark	Yes	ACP type not established	The building does have ACP material which is limited to small amounts fitted to the car park frontages considered to be trim. The building is fitted with a type 1 fire alarm system with smoke detectors
164-168	Hobson Street	Auckland Central	Fiore II	Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the front entrance canopy. The building is predominantly concrete with aluminium joinery. The building has types 7 & 4 fire alarm systems, smoke detectors, and automatic fire sprinklers
185	Fanshawe Street	Auckland Central		Yes	ACP type not established	The building is also clad in pre-cast concrete panels and glazing. The building has a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
19	Hargreaves Street	Ponsonby		Yes	ACP type not established	The building has a type 4 fire alarm system and smoke detectors
2	Emily Place	Auckland Central	Guildford House	Yes	ACP type not established	The building does have a limited amount of ACP cladding located at the front entrance to the building. The building has types 3, 14, 16 and 18 fire alarm systems and smoke detectors
207	Federal Street	Auckland Central	The Federal City Apartments	Yes	ACP type not established	The building is also clad in fibre cement sheet, Nuwall, precast concrete and glass. The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
21	Hargreaves Street	Ponsonby		Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the parapets. The building is predominantly clad in Fibre Cement sheet and textured blockwork. The building has types 3, 15, 16, and 18 fire alarm systems and smoke detectors
21	Laidlaw Way	East Tamaki		Yes	ACP type not established	The building does have ACP cladding, limited to the office frontage. The building is predominantly clad in 0.40 mm Colorsteel SteelSpan 900
23	Customs St East	Auckland Central	Citibank Centre	Yes	ACP type not established	The building does have some ACP material which is limited to small amounts fitted to the ground floor shop facades and canopy fascia. The building is fitted with a type 6 fire alarm system, smoke detectors and automatic fire sprinklers
23	Hargreaves Street	Ponsonby		Yes	ACP type not established	The building is also clad in Hardies Titan Board and glazing. The building has a type 4 fire alarm system and smoke detectors
27	Mackelvie St	Grey Lynn		Yes	ACP type not established	The building has a fire alarm system
277-305	Broadway	Newmarket	Westfield Shopping Centre	Yes	ACP type not established	The building is also clad in Fibre Cement sheets and concrete blocks. The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
28	Verissimo Dr	Mangere		Yes	ACP type not established	The building does have ACP cladding located as decorative features only. The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
30	Beach Road	Auckland Central	Scene 3 Apartments	Yes	ACP type not established	The building has types 2, 3, 7e, 15, 16 and 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
381-383	Broadway	Epsom		Yes	ACP type not established	The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
404-412	Khyber Pass Road	Newmarket		Yes	ACP type not established	The building has a type 3e fire alarm system and smoke detectors
5	Putney Way	Manukau	Westfield Manukau, Events Cinema	Yes	ACP type not established	The building does have a limited amount of ACP cladding located on the parapet. The building is predominantly clad in precast concrete, colour-steel and fibre cement panels. The building has a type 7 fire alarm system, smoke detectors, and automatic fire sprinklers
50	Centreway Road	Orewa	Pacific Building	Yes	ACP type not established	The building has types 4, 16 and 18 fire alarm systems and smoke detectors
6	Princes St	Auckland Central	Pullman Hotel	Yes	ACP type not established	The building has types 6, 7, 9, 15, 16, 18 and 20 fire alarm systems, smoke detectors, and automatic fire sprinklers
60	Airedale Street	Auckland Central	ICONZ	Yes	ACP type not established	The building has a Fire alarm system
60-70	Beach Rd	Auckland Central	Quay Park Health Building	Yes	ACP type not established	The building has a types 6 and 7 fire alarm systems, smoke detectors, and automatic fire sprinklers
64-68	Great North Road	Grey Lynn		Yes	ACP type not established	The building has a type 4 fire alarm system and smoke detectors
7	Island View Terrace	Cockle Bay		Yes	ACP type not established	The building is less than 10 meters in height and no building elevation is less than a meter from the boundary
72	Nelson Street	Auckland Central	Zest Apartments	Yes	ACP type not established	The building is also clad in concrete wall and glass. The building has types 2, 7e, 15, 16 and 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
72-78	Victoria Street West	Auckland Central	SkyCity	Yes	ACP type not established	The building does have a limited amount of ACP cladding. The building is predominantly precast concrete panels. The building has types 7, 9, 11, 14, 15 and 16 fire alarm systems, smoke detectors, and automatic fire suppression
7-9	Fanshawe Street	Auckland Central	Clearpoint House	Yes	ACP type not established	The building is also clad in pre-cast concrete panels and glazing. The building has a type 4 fire alarm system and smoke detectors
8	College Hill	Freemans Bay		Yes	ACP type not established	The building has a type 4 fire alarm system and smoke detectors
85	Airedale Street	Auckland Central	Edenz Colleges	Yes	ACP type not established	The building has a type 6 fire alarm system, smoke detectors, and automatic fire sprinklers
85	Beach Road	Auckland Central	The Beach	Yes	ACP type not established	The building is also clad in glass and Fibre Cement sheets. The building has a types 7e, 8, 9, 13, 15, 16 & 18 fire alarm systems, smoke detectors, and automatic fire sprinklers
85	Park Road	Grafton	Building 502	Yes	ACP type not established	The building is also clad in plywood, profiled metal cladding and glazing. The building has a type 3 fire alarm system and smoke detectors
95-99	Customs Street West	Auckland Central	The Quays	Yes	ACP type not established	The building does have a limited amount of ACP cladding, located on the soffit and parapet areas. The building has types 2 and 6 fire alarm systems, smoke detectors, and automatic fire sprinklers
85-89	Customs Street West	Auckland Central	Watermark Plaza	Yes	ACP type not established	The building has automatic fire sprinklers and a fire alarm system